

9 JUN 1960

Received from Chief Ship Surveyor

SHIP'S NAME "AURIS"

REPORT

a) ROT
b) NWC

49007
No. 116968

EA

Outstanding Conditions of Class: NONE.

S.R.L. Appendix. (As before or None)

Nature of Present Survey: ~~(At port and in dry dock)~~

Docking: a) Deferred repairs to contact damage.
b) Docking. Permanent/temporary repairs to damage
(various causes) including part S.R.L Appendix item.
and (a) above.

Recommendation: SUBMITTED record of DS 3,60 be assigned subject to indented shell plates F.7, G.8, H.8 & 12 (s.s.a) and to No. 1 shell plate in poop shear (p.s.a) and structure in way being specially examined and dealt with as necessary next drydocking.

DS 3,60 SUBJECT

S.R.L. APPENDIX (AMENDED).

Shell plates J.4, 5 & 6, H.4 & 5 (s.s.f)

and F.6 (s.s.a) indented.

Keel plating *ing* forward slightly wavy.

*2.5-2
26/5/60*