

Received from Chief Ship Surveyor 21 AUG 1953

SHIP'S NAME "EMPIRE CELTIC" REPORT Lon. No. 127521

Outstanding Conditions of Class: Subject to E.W. repairs to after corners of Nos. 1 & 2 hatchways being specially examined and dealt with as necessary next drydocking.

Endorsement of Class (B) (As before ~~XXXXXX~~)

Signature of Present Survey: (Afloat and in dry dock)

Docking: Damage repairs on account of heavy weather also conditions of class as above.

Recommendation: SUBMITTED record of docking 7,53 be assigned, subject to permanent repairs to bottom riveting of starboard centre transverse in No.16 tank by next drydocking, but without other condition.

7,53 Lon. Subject  
Without.

ENDORSEMENT OF CLASS (B).  
Indents in shell plating (p & s).  
Bottom plating fwd set up.

IN S.R.L.

(After part of vessel in way of skags to be specially examined each drydocking).

*Handwritten signature and date: 21.8.53.*

C.S.S. Records Dept.  
to note.



© 2018

Lloyd's Register  
Foundation