

REPORT of SURVEY for REPAIRS, &c.

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey

Aug 16

Last Survey

Recd 1.10.78

Sept 30 1878

1242 on the

SS Uryll

Master

J Scott

TONNAGE under Tonnage Deck

1911

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Q. Dk.

Ditto of House on Deck

Ditto of Forecastle

Gross Tonnage

1956

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

1271

Built at

Glasgow

When built

1875

YEAR.

MONTH.

Owners

J Warrack & Co

Port belonging to

Leith

Residence

By whom built

either

Destined Voyage

If Surveyed Afloat or in Dry Dock

Afloat

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

14275

Port

Leith

Classed

100 A 4.75

REPAIRS, OR EXAMINATION AS PER RULE

SS M-1, not completed

Cause of Repairs to be clearly stated.

At the present time the timbers and ceiling equal to one and more shanks have been taken up on both sides from forward to the brp coal bunker before the engine or boiler room, and from the engine room to aft examined and found in good condition, the cement tested which was adhering firmly to the iron.

The brp coal bunker has coals in.

The SS M-1 is not due in this case until next year but the owners desire to have her examined as far as practicable at present and will carry out the survey on her return to England from her present voyage

See Henry Hough report No 115 20/10/77 a further part of work done

Present Condition of the

Decks

Where seen

Good

Waterways

"

Comings

"

Upper Deck Beams & Fastenings

"

Lower Deck Beams & Fastenings

"

Planksheers

"

Sheerstrakes

"

Topsides

"

Wales

"

Plank (Bottom) and Counter

"

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

General Observations, Opinion as to Class, &c.

She is now in good condition and entitled to remain as Classed.

Henry Hough

Surgeon Master

The Amount of Entry Fee ...

£

2

2

2

2

2

2

2

2

2

2

2

2

Certificate (if required) ...

£

5

5

5

5

5

5

5

5

5

5

5

5

(Travelling Expenses, if any, £)

Committee's Minute

8th October

1878

Character assigned

100

J. B. W.

Surveyor to Lloyd's Register of British and Foreign Shipping.