

s.s. "CONTE ROSSO".

Loeffler Boiler and Escher Wyss Turbine Installation.

Regulating Valve

IT IS SUBMITTED the Firm be informed the remarks contained in their letter of the 16th instant are noted.

It appears, however, that this valve was made at a Steel Works which is not recognised by the Committee, and further that the material was not tested, and in these circumstances it is felt that the Society cannot accept any responsibility for this fitting.

It should be added that the Society's Surveyors at Trieste were advised to this effect as long ago as 24th March, 1936.

If, however, the valve is urgently required its use for the present could be agreed to provided a new valve, made under the usual conditions of survey and testing be ordered forthwith, and fitted as soon as possible.

Advise Trieste Surveyors.

Advise Vienna Surveyors.

19th May, 1936.



© 2018

Lloyd's Register
Foundation

str 20/5 4