

For the information of Surveyors and the Committee only.

Received at

Office 28 MAR 1930 19

Lloyd's Register of Shipping.

(Report on Vessel No. 40993. Port Hull)

No. SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings manufactured by Messrs T.S. Forster & Sons Ltd. of Sunderland for the Vessel No. 1083, being built by Messrs Buchanan & Sons Ltd. of Selly have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

Report on Forgings or Castings.

Lloyd's

No. 5754

27.3.30

J. Dale
Sunderland

STERN FRAME.

RUDDER FRAME.

STEM.

Material* ... Scrap iron
made ... Forged & Smithed
Dimensions ... 6 x 3 1/4
Process on Inspection ... Forging & Smithing
When Inspected ... 27.3.30

CASTINGS.

Tests on Standard Test Pieces.

Tensile Test—

Stress per square inch

Elongation per cent. ...

Bending Test—

Angle before fracture

Impact Test—


Height from ground ...

Welding Test—

Welds made according to Rules (and found satisfactory ...)

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Welds



Fee (if any chargeable) £

To be paid at

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

002000-002012-0193