

Received by Chief Ship Surveyor

18/10/09

Received from Chief Ship Surveyor

VESSEL'S NAME

St S Steerman

Rpt.

Two

No

57466

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	20'	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing:— Bulb angle, as approved. (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A1 (Sul) as recommended.

+ 100 A1 (Sul)

1st (Sul)

Hull class

W.B. 2 Bf 102 124 1/2 F.P.T 344

JK 3 Bf. Cum Lloyds A & C.P. Q80 3 1/4 F22 'Mch' Aft



© 2020 RBA

Lloyd's Register Foundation

002051-002061-0004

Recd. 5/11/47