

COPY.

Lloyd's Register of British & Foreign Shipping,
71, Fenchurch Street, E.C.

29th December, 1911.

Gentlemen,

E. With reference to Greenock First Entry Machinery
Report No. 16163 in the case of the S.S. "MONTORO" I shall be
glad to be informed whether two main bearing bolts have been
placed on board as spare as no mention is made of them in the
report.

I am, Gentlemen,

Your obedient Servant,

Secretary.

The Surveyors,
GREENOCK.



© 2020

Lloyd's Register
Foundation

002051-002061-0184