



LLOYD'S REGISTER
LONDON.

RECEIVED 30 AUG 1920
ANSD

Garama
Lloyd's Register of Shipping,

342, Argyle Street, Glasgow.

28th August, 1920.

Reference

S. Sir,

Reverting to your letter of the 21st instant respecting Greenock Report No.17681 on the S.S. "RONALD", I beg to acquaint you that the Surveyor states that through a clerical error the height of the outside brackets at the bilge above margin was stated in his report to be 47", instead of which it ought to be 50". This is accounted for by the 3" droop in the tank top. The riveting of the butts in the keel was as given in the report, and was arranged to suit the multiple punching proposed by the Builders, the rivet area being in excess of that required by the Society's Rules.

I am, Sir,

Your obedient Servant,

J. L. Warlow

Secretary to the
Glasgow Committee.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

002071-002078-0120

002071-002078-0121

