

Length of Ship on Loadline.....	<i>213.87</i>
Length in Table	<i>186.00</i>
Difference	<i>27.87</i>

CORRECTED
DIMENSIONS.*213.87*Rule.
*3-6
4-4
1-11*

THE BURNTISLAND SHIPBUILDING COMPANY LIMITED.

TELEPHONES:
WORKS: NO. 150 BURNTISLAND (2 LINES)
MANAGING DIRECTORS' RESIDENCES:
MR A. L. AYRE. NO. 219 CENT. EDINR.
MR. WILFRID AYRE. NO. 133 BURNTISLAND.

DIRECTORS:
A. L. AYRE. (CHAIRMAN)
WILFRID AYRE.
J. C. CLOUSTON.
ARGYLL LINDSAY.
C. R. ORR.
D. W. PATON.

OUR REF.
YOUR REF.

PLEASE ADDRESS THE COMPANY, NOT INDIVIDUALS.



LLOYD'S REGISTER
22nd July 1926
Recd. 23 JUL 1926
Add. LONDON

Telegrams,
SHIPYARD, BURNTISLAND.
Codes,
MARCONI INTERNATIONAL
SCOTT'S 10TH EDITION
BENTLEY'S.

Lloyd's Register of Shipping,
Fenchurch Street,
London, E.C.3.

Dear Sirs,

Ship No. 140.

With reference to the writer's call upon you yesterday when the question of the winter draft of this vessel was discussed, provided the moulded winter draft, which will result from the presented plans and particulars thereon, is no less than $14'-4\frac{1}{2}''$, it will not be necessary to make any modifications to the sheers.

Yours faithfully,

For THE BURNTISLAND SHIPBUILDING COMPANY LTD
A. Ayre
MANAGING DIRECTOR

In making this communication to You it is to be clearly understood you are in nowise authorised to offer the Vessel, or Vessels, referred to, and approved of by us, and confirmed by our usual Commission Note, to any one entitled to any commission, or otherwise, unless the name of the proposed purchaser has been first submitted to, and approved of by us, and confirmed by our usual Commission Note.

F/CF.



© 2021

002085-002093-0019

Indian Summer Line " "
Winter Line " "
Winter North Atlantic Line " "

* If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.

+ In vessels obtaining a certificate of classification.

State dimensions of freeing ports axes on back of this form.

Seek Hatchways efficiently constructed and at least equal to the
Section 28 of the Rules for 1904-5? Give particulars below:-

Check Hatchways efficiently constructed and at least equal to Section 28 of the Rules for 1904-5? Give particulars.

l to the }
below :— }

卷之三

WON 16-0 X 227 CORRECTED

16-0 x 22
" " "
3-22
Rule.
DIMENTI CORRE

(I) tables, state following information is the thickness.

Delete the
that do not

Fr.

2 March

Sb

special features

of sister ves

of sister ves
Auntie

In Steamship proprietors of Howard Smith & Son
33 Cornhill London

If the frames, skin plate
of ceiling should be
In vessels obtaining all