



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Royal Bank Buildings, 28, Constitution Street,

Leith, Edinburgh, 6

RECEIVED

9th June, 1956.

11 JUN 1956

Reference

WO/DP.

11/56

Dear Sir,

It is with very much regret that I have to report the substitution of the two memo's regarding the overdue surveys of the s.s. "JULIET DUFF" and the s.s. "FOLDA" of the 20th April, 1956. The information given for the "FOLDA" should have been for the "JULIET DUFF" and vice versa. These should read as follows:-

s.s. "JULIET DUFF" 23rd April, 1956.

The Owners inform us that the Loadline and Boiler Surveys on the above vessel were carried out at Blyth in February last. The vessel was Dry-docked in September, last but the Owners omitted to call a Surveyor in. The Owners state that they will make arrangements at the earliest opportunity to drydock the vessel.

s.s. "FOLDA" 23rd April, 1956.

The above vessel has been sold for scrap and will be broken-up at Interkeithing.

Yours faithfully,
THE SURVEYORS,
Per:-

Chas. G. G. G.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

002094-002100-0264

CLASSIFICATION

PUBLICATIONS

H

[Handwritten signature]

[Handwritten signature]

Let:-
THE CHAIRMAN,
LONDON

Dear Sir,
I have the pleasure to acknowledge the receipt of your letter of the 14th inst. in relation to the above-mentioned matter.

Yours faithfully,
L. J. B. [Signature]

The enclosed copy of the report of the Committee of Enquiry into the activities of the above-mentioned firm is being forwarded to you for your information. The Committee's findings are set out in the report and it is noted that the firm has been found to be in breach of the provisions of the Act of 1947. The Committee has recommended that the firm should be struck off the Register and that the name of the firm should be removed from the Register.

Yours faithfully,
L. J. B. [Signature]

The enclosed copy of the report of the Committee of Enquiry into the activities of the above-mentioned firm is being forwarded to you for your information. The Committee's findings are set out in the report and it is noted that the firm has been found to be in breach of the provisions of the Act of 1947. The Committee has recommended that the firm should be struck off the Register and that the name of the firm should be removed from the Register.

RECORDED

© 2020

Lloyd's Register
Foundation

Bank Building, 38 Corporation Street
LLOYD'S REGISTER OF SHIPPING