

We acknowledge with thanks your letter of the 24th February and are pleased to state that we were able

Lisbon.

SEL'S NAME S/S CAID ALIAL

Report Casablanca No. 4317

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in  $\frac{1}{40}$  of an inch.

STRAKE.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.
	Original Thickness.	Thickness by drilling		Diminution if any.	Original Thickness.	Thickness by drilling		Diminution if any.	Original Thickness.	Thickness by drilling		Diminution if any.	
		Port.	Std.			Port.	Std.			Port.	Std.		
		P	S		P	S		P	S				
DOE SHEER STRAKE.													
ke below . . . . .													
ER STRAKE . . . . .	H		15		16	14.5			15				
Strake below . . . . .	G		16			14.5			•				
" " . . . . .	F	15	16		15	16			16				
" " . . . . .	E	16	15		14.5	14.5		•	15				
" " . . . . .	D				15	16		16	17.5				
" " . . . . .	C	18.5	18.5		16			17	17.5				
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													
" " . . . . .													

Drillings at ends to be made in the vicinity of the peak bulkheads.

002101-002108-0050

Lloyd's Register  
Foundation