

*Glasgow 70912*

# Lloyd's Register of Shipping.

23 JUL 1946

## MERCHANT SHIPPING (SAFETY AND LOAD LINE CONVENTIONS) ACT, 1932.

### RENEWAL SURVEY IN ACCORDANCE WITH SECTION 48 (4) OF THE ABOVE ACT.

(Port) GLASGOW(Date) 16th July, 1946

I have to report that I have surveyed the \_\_\_\_\_

S.S. "LANCASHIRE" of Liverpool O.N. 140529

on this date.

I have compared the arrangements on board the ship with those given in the original freeboard report and I have found them to be in agreement therewith or equivalent thereto, and the whole to be in efficient condition.

Repairs: A number of wood hatch covers and hatch battens renewed.  
A number of side scuttles overhauled & re-rubbered.  
A number of discharge valves opened up & overhauled.  
-----

S. 2nd No.3 has been completed at this time and it will be recommended that the vessel is eligible to have fresh record of dry docking 7.46 and the notation of S.S. Gla. 7.46 (DR), subject to repairs to cruiser stern plating, etc. (p & s) being carried out at the first convenient opportunity.

The freeboard marking has been verified and found to agree with the freeboards given on memo of freeboard enclosed with London letter of certificate No. 22149 dated 27/5/46 Verification Form C.12(a) enclosed herewith. which is returned herewith Certificate No.22149 and certified copy returned herewith for cancellation.


*Geo. Lockburn*

Surveyor to Lloyd's Register.

Fee £5: 0; 0

Is fee paid \_\_\_\_\_

2m.2.46.



© 2020

Lloyd's Register  
Foundation

002157-002164-0063

Winter freeboard =  $\frac{a}{4}$  inches = ✓

= 6.27

Correction for Thickness of Deck amidships  
Other corrections, scantlings, etc. ...