

WARD REPORT on the

"Helix"

It is submitted the Rotterdam Surveys be advised that the above vessel is being transferred from French to British registry and in consequence a new British loadline certificate will be required. They should carry out an annual

loadline survey to verify the present. The new certificate copy should be forwarded for issue when this has been done.

A copy of the CII report should be sent for their guidance & should afterwards be placed on board the ship.

The Owners should be advised of the action taken.  
~~that~~

The French certificate  
should be returned  
for cancellation.

E.T.B.

28.10.38

Lloyd's Register  
Foundation

002206-002214-6210