

2m.11.35.

1

BANN QUEST.
Bois hard

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Screw "OPEPE" Report Gls. No. 58760

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

1100A1

1 Dk.

FPT 54t, APT 35t.

BK, 6", 3 BH, Cem., Lloyd's A & CP.


Q 81', B 7', F 20'

Machy. aft.

O.L. 148'1"

This is a sister ship ^{to the} "BAMBOO"

The Certificate of Classification is
be endorsed "Cargo battens not
fitted" and the same notation to be
entered in the Register Book



© 2021

Lloyd's Register
Foundation

002222-002228-0053