

List of spare gear, proposed by Messrs. Linke-Hofmann-Busch-Werke A.G., Breslau, for the auxiliary oil engines Nos. 1832-33, ordered by Messrs. N.V. Kon.Maats. "De Schelde" for the M.S. "BOSCHFONTEIN".

For both Motors together:

1 cylinder liner complete.
1 " cover with bolts and nuts.
1 set of main bearing brasses for one cylinder.
1 set of bolts & nuts for each dimension of main bearings.
1 set of fuel valves.
4 nozzles complete.
1 fuel pump cam, 1 roller with pins, 4 springs.
1 inlet valve complete.
1 spindle, 1 seat, 1 cam, 1 roller & 4 springs for inlet valves.
1 set of outlet valves complete.
2 spindles, 1 cam, 1 roller, 4 springs, 1 lever for outlet valves.
1 starting valve complete.
1 spindle, 1 seat, 1 cam, 1 roller, 4 springs for starting valves.
1 safety valve complete.
1 seat, 2 springs for safety valves.
1 set of brasses for cam shafts.
2 pistons with rings & pins.
2 sets of piston rings.
1 connecting rod with brasses, bolts & nuts.
1 fuel pump complete.
1 lubricating oil pump complete.
2 springs for regulator.
2 bolts & nuts of each kind for cooling water pump.
1 set of copper- & rubber packing rings.
1 set of pipes of each kind for starting air, fuel- and lubricating oil, complete with flanges.
1 set of breaking plates
40 assorted bolts & nuts.
6 holding down bolts.
Filter material for oil filters.

LINKE-HOFMANN-BUSCH-WERKE
AKTIENGESELLSCHAFT

H. Meyer
H. Schmidt



© 2021

Lloyd's Register
Foundation

002222-002228-0164