

ARTFORD.


Register of Shipping.

S.S. "CAMERONIA."PROPOSED LIST OF SPARE GEAR FOR TWO NO. 10a SEPARATE VERTICAL MARINE TYPE CO2 REFRIGERATING MACHINES TO THE REQUIREMENTS OF LLOYD'S REGISTER.

- spring rings for compressor pistons
- special metal packing rings for compressor gland
- set of 2 leather moulds
- compressor pistons and rods complete
- compressor delivery valves, seats and springs
- compressor suction valves, seats and springs
- additional valve springs
- spare spindle and disc for brine pump
- spare spindle and disc for water pump
- CO2 stop valves
- CO2 regulator spindle
- CO2 pressure gauge
- pair of bolts and nuts for crankpin bearing
- pair of bolts and nuts for main bearing
- pair of bolts and nuts for crosshead
- copper safety discs
- sets of copper joint rings for compressor joints
- set of copper joint rings for all other joints
- guide for grinding in compressor valves
- rawhide pinion
- fitted box for holding compressor pistons, valves, springs, rings, etc.
- lengths of wrought iron pipe each $1\frac{1}{4}$ " and $1\frac{1}{2}$ " bore
- wrought iron bends each $1\frac{1}{4}$ " and $1\frac{1}{2}$ " bore
- 12 sockets and 12 backnuts each $1\frac{1}{4}$ " and $1\frac{1}{2}$ " wrought iron pipe
- 1 pair of ratchet dies to screw $1\frac{1}{4}$ " and $1\frac{1}{2}$ " gas thread
- 2 pairs of CO2 pipe flanges
- assorted bolts and nuts
- dundry brine cocks
- 3 brass-cased thermometers
- 1 spring for CO2 safety valve.

ELECTRICAL SPARES :-

- 1 armature for 32 B.H.P. motor for driving CO2 machine
- 1 line of brush holders for do.
- 1 set of carbon brushes for do.
- 1 set of bearing bushes for do.
- 1 armature for brine pump motor
- 1 armature for water pump motor
- 1 line of brush holders for either brine pump or water pump motor.
- 1 set of carbon brushes for do.
- 1 set of bearing bushes for do.



© 2021

Lloyd's Register
Foundation

00019-002231B-0124