



Lloyd's Register of Shipping,

Lloyd's Bank Chambers,

Middlesbrough, *6th January 1915*

LLOYD'S REGISTER
LONDON
7 JAN 1915
REC'D
ANS'D

Reference

Sir

Referring to the Freeboard and
First entry reports of Messrs Wm Harker & Sons
"Arkleside" No 208 1/2 I beg to state that
the widths of the Main and Quarter deck
hatches should be 16'-11 1/2" and not 17'-11 1/2".
I shall be glad if you will amend this
on the reports. Regretting the error.

I am, Sir,

Your Obedient Servant
A. Phillips.

The Secretary
London.



© 2020

Lloyd's Register
Foundation


002289-002291-0063

982
5/12/14


Referred to the Chief Ship Surveyor.



JAN 7 1915
Also for Mr. S. A. Hill to note:



[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the paper.]



© 2020

Lloyd's Register
Foundation

BEAMS, I