



Please address
 further communications
 on this subject to
 THE SURVEYORS.

Lloyd's Register of Shipping. A.

Outdoor Surveyors' Office,

14, Trinity Square, London, E.C.3.

RECEIVED

22 JUN 1949

21st June, 1949.

Dear Sir, ANSD.....

With reference to your letter of the 7th instant regarding the survey of Messrs. Richards Ironworks Ltd., Yard Nos. 284/5, we have now received confirmation from the Shipbuilders that the fees for the survey of the engines during construction will be payable by Messrs. Crossley Brothers but that they (Richards Ironworks) will be responsible for the proportion of the fee for the survey during installation on board.

Yours faithfully,

THE SURVEYORS,

Per: *Morrison*

The Secretary,
 LONDON.

002330-002339-0099



© 2020

Lloyd's Register
 Foundation

If Plated, state thickness.....
Poop Deck.
 Stringer Plate, breadth and thickness.....

RECEIVED
 10/10/2020
 E.C.3.

Referred to the Chief Engineer Surveyor.

D. Dept

W. Moffitt to note
 noted
 Bell



© 2020
 Lloyd's Register
 Foundation

BULKHEADS.

FORGINGS AND CASTINGS.

26 ✓	S.R. ✓	5/8 ✓	2 7/8 ✓	S.R. ✓	5/8 ✓	2 1/4 ✓	STRAPPED ✓
------	--------	-------	---------	--------	-------	---------	------------

D