

Lloyd's Register of Shipping.

Ship's Name "NUEVO DOMINICANO" Official No.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

The following ventilators have now been removed and the openings efficiently blanked off by means of steel bolted plates on the shelter deck, on the port and starboard sides:-

Port Side of Shelter Deck:

- 36 ventilator openings 4 1/4" x 7" blanked off
- 1 ventilator opening 4 1/2" x 20" " "
- 1 ventilator opening 4 1/2" x 15" " "

Starboard Side of Shelter Deck:

- 31 ventilator openings 4 1/2" x 7" blanked off
- 4 " " 4 1/2" x 20" " "
- 1 " opening 4 1/2" x 15" " "

Y. J. Gendley

Surveyor to Lloyd's Register of Shipping

August 23, 1949

Noted
28 SEP 1949