

5c.11.49.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

BRITSUM.

VESSEL'S NAME

REPORT

Rot.

No. 32332.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH--~~

The heating surface of the new superheaters installed is now given as 968 sq. feet total.

1mb
Amend in R.B.

H.S. 8366.

MN 550.



© 2020

Jm
6.7.50.

Lloyd's Register
Foundation

002435-002441-0061