

174 FEB 1957

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME *CABLE ENTERPRISE* REPORT *PLY.* No. *8517.*

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD.

MC
MC(M) due *7.54*, partly held *now*.
18
BS

now further advanced and the following repairs effected (due to *W & T.*
 both boilers examined internally & externally, together
 with securing arrangements. Condition found good,
 except a few tubes which should be renewed before the
 vessel is placed in commission. This examination was
 made in order to ensure that the boilers were in a state
 of preservation.
 It is proposed to complete the Survey when the vessel is placed
 in commission.

It is submitted that this proposal merits approval and the vessel is
 eligible to remain as classed, and WILL BE eligible for the record

B.S. 1,57. when the Survey has been completed.

The following remains to be done to complete the Survey.

Tube renewals as found necessary.
 Safety valves to be examined.
 Mountings, doors & fastenings to be examined.
 Safety valves to be adjusted under steam.
 Oil burning system & remote controls to be examined
 working in accordance with Rules.

Vessel laid up at Plymouth.

002442-002448-0172

© 2021

Lloyd's Register
FoundationRh. 1-2-57.
accu