

Wreck Report No.

15714

REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 54037 in R.B. Wreck Book, p. 47/61

Date of writing this report

8th March,

19 61.

Ship's Name

m.s. "BERNY"

of

Mariehamn

Built at

Martenshoek

When

1950

MONTH.

3

Casualty notice sent to Owner

Owner's reply

Owners

Managers

Address

SOURCE OF INFORMATION

BERNY. — Gothenburg, Feb. 17. — Panamanian steamer TYNE collided with Finnish motor vessel Berny (Skutskar for Manchester and Preston) in fog near Laeso N. Light-vessel late on Feb. 16. Berny sank; crew saved by TYNE and brought in here.

Stockholm, Feb. 17. — Gothenburg radio station reported early to-day that motor vessel Berny had sunk three miles off the Danish island of Laeso following a collision last night with steamer TYNE. The crew of the Berny were taken on board the TYNE, which received only minor damage, the report said.—British United Press.

LL 18/2/61

Classification details

+100A1	+LMC CS5,60
5,60	
ss 5,60	ts 5,60 OG
Reclassified 8,56	

of Casualty

16th February, 1961.

s of Casualty

This ship was sunk by collision near Laeso Nord Lightship and is a total loss.
The owners concur.



Suggested Record

"SUNK BY COLLISION 2,61"

Date of Committee

FRIDAY 10 MAR 1961

Committee's Minute

Sunk by collision 2.61

1m,11,58