

7 JUN 1960

Received from Chief Ship Surveyor.....

SHIP'S NAME "BERNY" REPORT Abo. No. 278

GB

Outstanding Conditions of Class: SUBJECT to indented side shell plating etc. (p & s) being repaired by the Special Survey.

S.R.L. Appendix. (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (C) due 9,60.

Nature of Present Survey: (Afloat and in dry dock)

Docking: Special Survey: Permanent and deferred repairs to damage on account of ice and grounding including S.R.L. and Appendix items.

Special Features:

Is Interim Certificate in order (Yes-No-None) ~~XXXXXX~~

Items Outstanding: (If any for S.S.)

NONE.

S.S. to ~~be~~ completed by ~~xxx~~

Recommendation:

SUBMITTED record of 'DS 5,60' and Notation of 'SS 5,60' be assigned, but without special condition.

DS 5,60
SS 5,60 Without.

S.R.L. APPENDIX NOTE (AMENDED).
Shell plates B.7 & 8 (s.s.f) indented.

FREEBOARD SURVEYORS TO NOTE.

DFC
9/6/60



© 2020

Lloyd's Register Foundation