

3 NOV 1956

Chief Ship Surveyor Received from Chief Ship Surveyor

SHIP NAME "BERNY" ex "BERGO" REPORT Cpn. No. 15920

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5,92.)

This ship was built in 1950-3 and then classed #100A1.

She was subsequently reported to have stranded on rocks and sunk in the Gulf of Bothnia.

The Notation "Stranded & Sank 12,54" was posted 18.1.55.

The COPENHAGEN Surveyors report (8,56), this ship examined in dry dock, bottom coated and the requirements of RECLASSIFICATION SPECIAL SURVEY (C) complied with.

On account of damage due to grounding and ice, repairs effected to keel, bottom and side shell plating, framing, floors, etc. and to the Endorsement of Class (B) items previously recorded against the ship's class.

The Surveyors further report the ship has been lengthened at this time approximately 11' in accordance with Rule requirements and approved plans.

They also report an additional 30 fathoms of chain cable supplied and verified on account of the increased equipment numeral.

The ship has been found to have all her previously supplied equipment on board.

The upper deck plating has been reinforced at this time by the fitting of a longitudinal girder and doubling plate between hatchways as per approved plan.

IT IS SUBMITTED ship is eligible to her class of #100A1 reinstated in the Register Book and to have record of docking 9,56 and Notation of 'ss.Abg. 9,56' assigned.

REINSTATE CLASS IN R.B.

#100A1
,56 Abg.
s.Abg. 9,56
eclared 8,56
en.8,56.

Noted
for
Header



© 2020

Lloyd's Register
P.T.O.
Foundation

002457-002464-01462

- 2 -

"BERNY"

1 dk; Str.Nav.Ice; pt E.W.
DB t; FPT 53t; APTs 16t.
FK; 3BH; LACP.
Q 39' F 27'
Mchy Aft
O.L. 195.7'
Extreme breadth: 29'-2"
Rise of floor: Nil
Rdr
(i) 1.1/8"

L. 167' B 29'-0" D. 13'-2½"

IT IS FURTHER SUBMITTED the Surveyors be requested to furnish the capacity of No.3 D.B.tank prior to the lengthening of ship in order that the correct water ballast capacity might be inserted in the Register Book.

MR. J.URWIN. *to note*

C.S.S. Records Dept.

to note.

Ship lengthened.

SAR.

8-10-66.



© 2020

Lloyd's Register
Foundation

002457-002464-0146 ²/₂