

LLOYD'S REGISTER OF SHIPPING

Port C A R D I F F12th March, 1959

This is to Certify that I have
 Donkey part of the
 Surveyed the Boiler and Machinery of the M.S. "BROOMDALE",
 3562 tons gross of London, whilst in dry dock and afloat at
 Barry on the 29th December, 1958 and subsequent dates for
 Docking, T.S. DBS. and C.S.,

and that I have transmitted to the Committee of Lloyd's
 Register of Shipping, London, a Report stating that all
 recommendations made by me in connection therewith have
 been carried out to my satisfaction, and that I have

Recommended that the record of TS.(CL) (Tailshaft Survey-
 Continuous Liner,) 3,59, DBS. (Donkey Boiler Survey) 3,59 now
 and C.S. (Continuous Survey of Engines) with date

be made in the Register Book in the case of this vessel when
 the survey has been completed.

Parts now examined :-

Propeller, stern bush, sea connections and outside fastenings.
 Screwshaft.
 All cylinders, covers, pistons, rods, valves and gears,
 connecting rods, top ends and guides, crankpins and bearings,
 journals and bearings.
 Thrust blocks, shafts and bearings. Intermediate shafts and
 bearings.
 Holding down bolts and chocks.
 Auxiliary condenser.
 M.E. lub. oil and fuel surcharge pumps.
 Crankcase doors and explosion relief devices.
 2 feed pumps, 2 O.F. unit pumps, lub. oil pump, Aux. fuel
 oil pump, O.F. transfer pump, bilge pump, aux. circ. pump,
 general service pump.

John Douglas
 (John Douglas) Engineer Surveyor to Lloyd's Register

Contd...

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."