

f Surveyors.....

Received from Chief Surveyors.....

NAME "BALLYHALBERT"

REPORT

Gls.

No. 88484

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey Docking: Special Survey (D) ~~xxxxxxx~~ (Ship 38 years old).  
Damage repairs.

NOTED.

Subject to sternframe solepiece (E.W. 4,58)  
being specially examined at the next drydocking.

DS 4,58

SS Irv. 4,58(Dr).

*LG*

*Am 30.5.58*



© 2020

Lloyd's Register  
Foundation

002515-002521-0032