



LLOYD'S REGISTER OF SHIPPING

95, Bothwell Street, Glasgow, C.2

Telegrams: Register, Glasgow, Telex
Telex No.: 77530

Telephone: Central 6491 (7 Lines)

Copy ltr. enclosed.


31st December, 1959.

Reference
.....

Dear Sir,


"BRIGADIER".

Thank you for your letter of the 29th
December in respect of the tailshaft survey.

Mr. Peace who carried out the inspection
at Glasgow in April, 1959 (Glasgow Report No.89905)
is now stationed at Cadiz. As the Owners subsequently
requested that the withdrawal of the tailshaft for the
fitting of a new oil gland be accepted for the tailshaft
survey, Mr. Peace was asked for his comments.

I enclose a copy of his reply, and regret that
this was not forwarded with Greenock Report No.26534.

Yours faithfully,


Secretary to the
Scottish Committee.

16/12
The Secretary,
LONDON.

002522-002528-0172

© 2020
Lloyd's Register
Foundation

ER CLASSIFICATION

H
M

Submitted record
of S-4/59 be assigned
Q 6/1/60



© 2020

Lloyd's Register
Foundation