

COPY

LLOYD'S REGISTER OF SHIPPING,
14, Cross-shore Street,
GREENOCK.

10th November, 1955.

Dear Sir,

Tug "BRIGADIER".


With reference to Greenock Report No. 25504 concerning the above tug, the oil gland at present fitted to the tailshaft is similar to that fitted on the Tug "THUNDERER" during June of this year and reported on Greenock Report No. 25407. The details of the "THUNDERER's" oil gland were submitted to London and the oil gland was not accepted as an approved type, the Owners being notified accordingly.

It is understood that the present oil gland was fitted to the "BRIGADIER" during a weekend dry docking in this Port, no request being made for the attendance of a Surveyor.

Yours faithfully,

(Sgd.) A.R. Morton

The Secretary,
GLASGOW.



Lloyd's Register
Foundation

002522-002528-0192