


COPY.

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER



Port NEW ORLEANS, LOUISIANA

25 April, 1958

This is to Certify that I have

Part

examined the ~~Boiler~~ and Machinery of the Steel Sing. Sc. Stmr.

"NTIDA" 4191 tons gross of Ceiba whilst lying afloat at this port
repairs to After LP valve

that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

amended that the record of Main Engines Survey 11,57


is entered in the Register Book in the case of this vessel.

Original
Wm. G. COWIN

Engineer Surveyor to Lloyd's Register.

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
Committees of the Society use their best endeavours to ensure that the functions of the Society are properly understood that neither the Society nor any Member of any of its Committees is under any circumstances held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of the Surveyors or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

PRINTED IN U.S.A.



Lloyd's Register
Foundation

007529-007535-0102