

Fees paid
Brunham

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stt. Sc. "OLYVIA"* Rpt. *hdb* No. *15225*



The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st. Long
~~Transverse~~ No. *2370*Depth "d" */*Framing: Table No. */*Description *Angle frames, as approved**2nd* Longitudinal No. *6557*Proportions */*
Length
Depth =~~Deck~~ Sheerstrake *as approved**Some additional strengthening has been fitted to shell framing
& centre line bulkhead in bunker & fish room.*This vessel appears to have been built in accordance with the
Rules ~~and~~ the approved plans *& Secretary's letters,* and it is submitted she is eligible to
be classed

✠ 100A.1 "Steam Trawler"

1 Dk

*DB 25'30t, Side tanks in ER
BK. 7½" 4BH, Gen, Lloyds A & CP.
Q. 86, F. 28.**circum letters before posting*
, APT 13tLloyd's Register
Foundation

002536-002542-0016

No notation of F.W. als
necessary (per W. Y.)

[Red scribble]

0 18' 30" 100' 22 80
0 18' 30" 100' 22 80
0 18' 30" 100' 22 80

921 1

1000 1000 1000 1000

then the observed value is to be entered the is eligible to
this lesser value to have been paid in accordance with the

... and in ...

Debit -
Probitone

prescription ...
Debit "A."



© 2020
Lloyd's Register
Foundation

E.F

TELEPH