

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port BOMBAY

20TH JUNE 1957

This is to Certify that I have

Surveyed the M.V. "BRITISH CHARACTER" 8461 tons gross of
London as she lay afloat in Bombay Harbour, for damage stated
to have been sustained at Kwinana, Western Australia on
28/5/57 when vessel's bow made contact with quay wall
and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have Recommended that she be continued in her present
class without fresh record of survey, subject to damaged stem
bar and stem plating at 1st & 2nd strakes below sheer being
specially examined and dealt with as found necessary by the
end of November 1957
being fit to carry petroleum in bulk.


A. Shkeman

Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

t. B.) 50m, 6.55. . . (MADE AND PRINTED IN ENGLAND)



Lloyd's Register
Foundation

007554-00067-0151