

(Electric Light Report)

M.V. "SILVERLARCH" - Newcastle Report No. 78237.

(Swan, Hunter & Wigham Richardson Ltd.).

Extract from letter dated 30. 9. 25) from Mr. Badger (Nwc)  
to Mr. Carnaghan.

-----

Lead covered and armoured cables in engine room  
and for main cables for and aft. The mains are clipped along  
on the underside of the upper deck in the tween deck space,  
this vessel having two tween decks in addition to the  
holds. The tween deck space where the cables are fitted  
is really a working space giving access to mail, provision  
and store rooms.

-----



© 2020

Lloyd's Register  
Foundation

002568-002576-0071