

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

SHIP'S NAME

"EMPIRE DORIC"

REPORT

Cls. No. 87419

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

"Laid up - Surveys overdue" is recorded in the Register Book.

See also endorsement dated 14.3.57.

The GLASGOW Surveyors report this ship examined in drydock, primarily for the purpose of an "Off-Survey" prior to being handed back to the M.O.T. on completion of charter.

This ship was examined generally internally and externally to ascertain as far as practicable the general condition of the ship's structure to enable a decision to be reached by the Owners as to whether or not the overdue Special Survey (C) (due 9,56) should be carried out.

Due to damage also wastage, extensive repairs are required to the shell and deck plating also to the structure in way of the tanks and other items. Only minor repairs have been effected at this time.

On undocking the ship was again laid up pending Owners' decision regarding the overdue Special Survey.

The case has been transmitted to London by the Glasgow Committee.

IT IS SUBMITTED that no further ACTION is required meantime.

AM.  
23.9.57



© 2020

Lloyd's Register  
Foundation

002568-002576-0136