

F.E.

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

EL'S NAME Steel Screw "ARCTIC PIONEER" Rpt. Hul. No. 47686

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

st Long. No. 2482 Depth "d" --
nd Long. No. 7034 Proportions = $\frac{L}{D}$ --
Framing Bulb angle frames as approved Sheerstrake As approved

This is a sister ship to the "ARCTIC EXPLORER"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 Steam Trawler

1 Dk.

DTf 4' 10t.

BK 8", 4 BH, Cem., Lloyd's A & CP.

Q 88' F 27'

Note: Overall length = 187.5'

W.D.
J.M.
31.3.37



© 2021

Lloyd's Register
Foundation

002577-002582-0097

