

"DARKA"

Lon. 2083
Gls. 72997

IT IS SUBMITTED that this vessel's Refri-
gerating Installation is eligible for the Record
* LLOYD'S RMC 6.48.

In the absence of any documentary evidence
in this office that the fan motors have been constructed
and tested in accordance with the Rules it is concluded
that this is so.

Should this not be the case the Glasgow
Surveyors should satisfy themselves that the fan motors
accord with Rule requirements in regard to construction
and performance under working conditions before issuing
the certificate to the Owners.

See also Secy. letter to Gls. 19.4.48.

CERTIFICATE WRITTEN.



28. 6. 48.



© 2020

Lloyd's Register
Foundation

002583-002591-0246