


"PLYM"

Before this case is submitted for the consideration of the Committee the Surveyors should be asked to confirm that the oilge suction pipes throughout the vessel are not less than $1\frac{1}{2}$ " bore as required in the Secretary's letter of 9. 4. 48 and on the approved drawing.

J.S.

13. 12. 48.



© 2020

Lloyd's Register
Foundation

002592-002601-0019

Air Mail Syd: - 14/12