

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Cert.No.3015

Port BREMEN.

6th July, 1957.

*This is to Certify that I have*

*surveyed the M.V. "ESSO BOLIVAR", 10728 tons gross of Hamburg, as  
lay in drydock at Bremerhaven on the 7th May, 1957 and subse-  
quently, for a docking survey and damage repairs to shell and keel  
plating. Damage stated to have been caused due to grounding in the  
River on 19th December, 1956, and in the San Juan River on the  
2nd November, 1956,*

*that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all repairs  
recommended by me have been completed to my satisfaction, and  
that I have Recommended that she be retained as now classed  
in the Register Book with fresh record of Docking Survey 5/57,*


*being fit to carry petroleum in bulk.*

*G. R. Matthews*

Surveyor to Lloyd's Register

(G. R. Matthews)

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be  
understood that neither the Society nor any Member, any of its Committees is under any circumstances whatever to be held responsible for any  
entry in the Register Book or other publication of the Society or report or certificate issued by the Society or its Surveyors, or in any way on judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents



Lloyd's Register  
Foundation

002602-002610-0066