

[Main Copy for attaching to Report.]

Lloyd's Register of Shipping.

Port C A R D I F F.

18th May, 1957.


Dear Sirs,

With reference to the
survey now being held on the ~~Steamer~~
m.v. "ASTURIA"

I beg to inform you that, in consequence of
the condition of this vessel's tie bolt
between Nos. 2 & 3 M.E. cylinders (p.s.)
it will be my duty to recommend to the Com-
mittee that the same be re-examined
before the end of May, 1958
provided for in the Rules, extracts from
which appear on the other side:—the con-
tinuance of the vessel's character in the
Society's Register Book to be subject to the
fulfilment of this condition.

I am,

Yours faithfully,


Engineer Surveyor to Lloyd's Register.

Messrs. K. Salvesen & Sonner,
P.O. Box 13,
Kragero,
NORWAY.

002602-002610-0116