

Lloyd's Register of Shipping.



Port KINGSTON, JAMAICA, B.W.I.

30th June 1959.

This is to Certify that I have

Surveyed the temporary repairs to the Hull Plating of the M.V.

"FLAMMULINA" 8197 tons of London

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued in her present class of F100A1 without fresh record of survey

being fit to carry petroleum in bulk, subject to permanent repairs being effected at the next drydocking.

(sgd) EDGAR WATSON. *EW*

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."