

10.59  
SPECIAL SURVEY (C) due 12,60. Postponement until 12,61 approved 17.11.60  
ACTION is DEFERRED for Special Survey and pending receipt of further  
information regarding breaking up.

nt to Chief Surveyors.....  
Received from Chief Surveyors.....  
SHIP'S NAME "FEDERAL VOYAGER" REPORT Boa. No. 4431

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**


In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

ature of Survey Temporary repairs on account of ~~When due~~  
contact damage.

NOTED.

SUBJECT to set in shell plating etc. in way of  
No.1 hold (p & s) No.2 hold (p.s.) and forward (p & s) also to  
set in shell plates JA 1,2 & 3 (s.s.a) being examined and dealt  
with as necessary by the Special Survey, to indented shell plating  
(p & s.f.) being examined and dealt with as necessary before loading  
another cargo and to fractured shell plating in way of No.1 'tween  
deck between frames 7 & 13 (s.s.) by 11,61.

ACTION is DEFERRED for Special Survey and pending  
receipt of further information regarding breaking up.



© 2020  
28/9/61

Lloyd's Register  
Foundation  
002611-002619 0190