

The class is subject to the starboard sea suction valve chest in the after Pump Room being renewed at the next dry docking.

4E

10.1111 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... EXTREMA..... REPORT Msl No. 12403

*D.B.S. due 5.58 now held*

CS Advanced.

Docking. Tailshaft seen.

SRL. The above item dealt with.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of TS (CL) 5.58 without special condition.

*and D.B.S. 5.58 now.*

*check for D.B.S.*



© 2020

Lloyd's Register Foundation

00611-00810-0130