

24 MAY 1960

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME "EL MOEIN" REPORT ADN No. 2880

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

8,59. The Notation "drydocking overdue" - class suspended

The class is subject to 15 fathoms of chain cable being supplied as soon as possible.

There is an S.R.L. Appendix note.

The Aden Surveyors in a cable dated 30.3.60 stated Owners requested certificate for one voyage Aden to Italy where ship to be scrapped.

London reply dated 31.3.60 stated unless G.E. was held in drydock no certificate to be issued.

The Aden Surveyors now report (4,60) ship examined afloat and in drydock and the condition of same found satisfactory for the contemplated voyage.

In view of the above, it is submitted a record of DS 4,60 be assigned subject as above.

DS 4,60 SUBJECT

DELETE FROM R.B.

Drydocking overdue- class suspended 8,59.

S.R.L. APPENDIX.

Rudder head twisted 3°.

Attch
16/5/60



© 2020

Lloyd's Register
Foundation

002620-002630-0266