

The class is subject to the top water box of piston water  
er and water end chamber of the cofferdam pump in engine being  
wed by 10.57.

4E

26 NOV 1957

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

E "ENSIS". REPORT Sng. No. 12266.

DBS due 10.57, now held.

C.S. Advanced. Docking.

SRL : Piston cooling water cooler waterbox has been renewed.  
deleted. New waterend for Engine Room cofferdam pump not  
delivered, existing water end examined and found satisfactory  
the meantime. The Surveyor recommends the cofferdam pump  
renewed by 10.57.8

Some engine and boiler repairs carried out.

IT IS SUBMITTED that this vessel is eligible for THE  
D, DBS 10.57, subject as now recommended, without other  
special condition.

CALL  
22.11.57.



© 2020

Lloyd's Register  
Foundation

002630-002638-0244