

Steel Screw

F.E.

Received from Chief Ship Surveyor

Steel Screw "ENSIS"

Rpt.

Rot.

No. 25269

Surveyor are desired on this case for the consideration of the Classing Committee.

Concise summary of any repairs that have been required and to show the cause or causes of such repairs, and also exceptional features in connection with the case, so that the Classing Committee may have all the salient points.
— Extract from Sub-Committee's Report. 24/5/92.

13175

Depth "d"

--

No. 36231

Proportions = $\frac{L}{D}$

13.7

As approved

Sheerstrake As approved

This is a sister ship to the "ETRENA"

002630-002638-0246

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed 1100A1 'Carrying petroleum in bulk'

1 Dk. 2nd Dk. clear of cargo tanks, 'Longitudinal framing at bottom and at deck'

Cell. DBUE 63' 132t, DTF 25' 257t, FPT 103t, APT 55t.

PK, 16 BH, Lloyd's A & CP.

27', B 38', F 48'

Length (Circular 1703) 446.3'.

JD
23.2.87



© 2020

Lloyd's Register
Foundation

Handwritten scribbles or initials in the top left corner.



© 2020

Lloyd's Register
Foundation

RU