

Received from Chief Ship Surveyor

31 MAR 1959

SHIP'S NAME
AR.

"CLYDEBANK"

REPORT H. Kg.

No. 14765.

Standing Conditions of Class:

None.

Exemption of Certificate (~~AS before~~ or None)

Condition of Present Survey: (Afloat and ~~in dry dock~~)

Temporary W & T repairs to shell plating in way of main engine discharge (s.s)

Recommendation:

SUBJECT to shell plating in way of main engine discharge (s.s) (wasted & doubled) being specially examined and dealt with as necessary by 4,59.

As now. Subject.



73
21-3-59
© 2020

Lloyd's Register
Foundation

002639-002646-0304