

Gross Tonnage 4279.66

Depth to 2nd deck 28.58 feet.
1st Longitudinal Number (L x D) F.S. Vessel 15531

Managers

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 0220
0221
0222
0223 } WHITEHALL-4

Lloyd's Register of Shipping,

17 Battery Place,
New York.



Please address further communications on this subject to THE PRINCIPAL SURVEYOR

LOYD'S REGISTER
Received
26 JAN 1943
LONDON

December 29, 1942.

Dear Sir:

- "OCEAN MESSENGER-N.Yk. 43110 (Tto.Mchy.Rpt. 884)
- "OCEAN COURIER " " 43111 (Mtl. " " 5737)
- "OCEAN GALLANT " " 43112 (Tto. " " 875)

The American engines built under survey and originally assigned to these ships were transferred to the United States Maritime Commission and the engines referred to in Montreal and Toronto reports mentioned above were later supplied in lieu.

The Montreal and Toronto Offices have, therefore, rendered their account of fee and expenses for the survey of each of these engines as shown on their reports and in their returns.

These fees have not been shown on the New York Reports or Rough Fee Book. Accounts should be rendered to the Admiralty for the agreed sum of \$4030.00 per ship, as shown on the above mentioned reports.

I am, Dear Sir,

Yours faithfully,

Principal Surveyor.
U.S.A. & Canada.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

002647-00652-6217

Spacing

Referred to the Chief Engineer Services

P. 26

Also for Mr. Nancarrow to note.

Also for Mr. Huxton to note.

26 JAN 1943

[Handwritten signature]

[Faint, mostly illegible typed text, possibly bleed-through from the reverse side of the page]

RECEIVED
1943
JAN 26
11 11

RECEIVED
1943
JAN 26
11 11

New York

11 11

11 11



© 2021
Lloyd's Register
Foundation

RECEIVED
1943
JAN 26
11 11

RECEIVED
1943
JAN 26
11 11