


COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Rpt.No.196



Port EMDEN,

28th January, 1958.

This is to Certify that I have

Surveyed the Boiler ^{Part} and Machinery of the S/S "AYDIN", 7715 tons gross of Istanbul/Turkey, whilst lying afloat at Emden on the 7th January, 1958 and subsequently, on account of boiler repairs,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of Main Boiler Survey 1/58 when the safety valves of both boilers have been adjusted and the O.F. burning installation examined working,

be made in the Register Book in the case of this vessel, subject to the main propulsion gearing to be examined not later than May 1958 (4 mos. limit).

For G.Maskos & self:-


H. Bornholdt

Engineer Surveyor to Lloyd's Register

(H.Bornholdt)

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

50m, 0.55. (MADE AND PRINTED IN ENGLAND)



Lloyd's Register
Foundation

001653-001658-0176