

implied if nec  
should be sumn  
Repairs on acco  
from Repairs a  
should be sumn  
Plating is drille  
Cables are rep

MEMORANDUM

**LLOYD'S REGISTER OF SHIPPING**, 71, FENCHURCH STREET,  
LONDON, E.C.3.

R  
(Ref. ~~XII~~.)

he Surveyor(s) at **KARACHI**

Date: **20th July, 1961.**

's Name : **s.s. "FORMA" 10 AUG 1961**

QUESTION	ANSWER
<p>With reference to your Report No.3215, I shall be glad if you will confirm that this tug is still out of service and laid up.</p> <p><i>mod</i></p>	<p><i>[Signature]</i></p> <p>Date:— <b>7th August, 1961</b></p> <p>The Owners confirm by letter dated 4th instant that the vessel continues to be laid up at Karachi.</p> <p><i>[Signature]</i></p>

*Red. 24.7.61*



© 2020

Lloyd's Register  
Foundation

002659-002666-0022