

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME..... "FULHAM".....
REPORT..... Nwc..... No. 114.658.


MBS due 8.57, now held.
DBS due 8.57, now held.

Docking. Screwshaft seen. A new spare screwshaft
w fitted. Some boiler repairs effected.

RECORD, IT IS SUBMITTED that this vessel is eligible for THE
MBS 9.57,
DBS 9.57,
TS(N)OG 9.57.



adm
3.10.57.



© 2020

Lloyd's Register
Foundation

002659-002666-0078