

Received from Chief Ship Surveyor

25 SEP 1958

SHIP'S NAME "CARROWDORE" REPORT Bel. No. 16515.
AR.

standing Conditions of Class: Subject to indented shell plating, framing etc. in way of F.P.space (p.s) being dealt with as found necessary by next drydocking.

Alteration of Certificate (~~As before or~~ None)

Result of Present Survey: (Afloat and in dry dock) Drydocking; repairs to shell plating etc. on account of collision damage, deferred item above; W & T repairs.

Recommendation: SUBMITTED record if 'DS 8,58' be assigned as recommended, without special condition.

DS 8,58. Without.



© 2020

Lloyd's Register
Foundation